

December 26, 1984

**EXECUTIVE SUMMARY** Atkins Mine MND980609903

## Situation

The Atkins Mine in Kinney, Minnesota operated in 1943 and 1944. Natural iron ore was mined from the site. It is not known if hazardous waste materials were generated from the mining operations. However, it is probable that used machine oil, e.g. crankcase oil, was disposed of onsite, but quantities and locations are not determinable.

There has been no report of the presence of contaminants in wells within a three mile radius.

## Inspection Priority Recommendation

Because of the short time the mine was in operation, problems arising from the Atkins Mine operations are not anticipated. However, low potential hazard is recorded in Part 1, V of the Preliminary Assessment because the town of Kinney is within one and one-half miles of the site. Thus, a low (pending) inspection priority is recorded in Part 1, V.Ol of the Preliminary Assessment. However, this priority is subject to change should information that might be obtained in the future indicate.

EPA Region 5 Records Ctr.

## Division of Solid and Hazardous Waste Site Response Section

## 3012 File Memorandum

Page 1 of |

File/Site Name Atkins Mire	I.D. No. MDD920603403
Active to Investigator Thomas	Date <u>• 1-14-25</u>
SOURCES OF INFORMAT	ION
Persons Contacted/Location/Phone No.	File Number(s)/Location
1) Michael Rickerali (Riker-dee)/ Uniland	Stat Mining Co. (218) 749-5910
3)	
4)	
5)	
ADDITIONAL INFORMAT	ION
I and the property of the one with and the sure beam indistring and by disposed through they disposed through they do not know for ourse. The perocess a minima of the one are high a way herewell and the row ste through out	ughout the runing area. However ving of the one was done at the enought that the overburden
<u> </u>	

